CPAP/ BiLevel CLEANING AND REPLENISHMENT INFORMATION

Thank you for your purchase of CPAP/ BiLevel equipment from MedPro Respiratory Care! The following information will assist you in ensuring your equipment is functional and clean while you continue with your CPAP/ BiLevel therapy.

• Your Mask

- Cleaning: It is recommended that your silicone CPAP/ BiLevel mask cushion be rinsed with water on a daily basis and the entirety of the mask be washed with a gentle soap and water once per week.
- Replenishment: Your mask should be replaced every 6 to 12 months due to normal wear and tear. Most extended
 health benefits plans reimburse their reasonable and customary amount for a mask on an annual basis. If you are
 unsure of your eligibility, call your extended medical plan to confirm your coverage.
- Warranty: 90 days

Your Humidifier Chamber

- Cleaning: The water in your humidifier chamber should be emptied and refilled on a daily basis. The humidifier chamber should be hand washed with a gentle dish soap and warm water twice per week.
- **Replenishment:** It is recommended that the humidifier chamber be replaced once per year or if it is leaking water/noticeable mold is developing in the chamber.
- Warranty: 3-6 months

Your Tubing

- Cleaning: Your tubing should be washed in a gentle soap and warm water once per week. To clean your tubing, fill
 up a clean sink or large container with the warm soap and water, fully submerge your tubing and gently swish it
 through the water, rinse your tubing and hang it to dry.
- **Replenishment:** Your tubing should be replaced on an annual basis or if it has torn/is no longer staying connected to your mask.
- Warranty: 90 days

Your Filter

- O Cleaning: The filter should be checked monthly to ensure it is not saturated with dust/pet hairs. Fisher Paykel and ResMed filters are not washable. Respironics filters can be washed with a gentle soap and warm water.
- Replenishment: Your filter needs to be replaced monthly or sooner if you think it is too dirty.

• Your CPAP/ BiLevel Machine

- Cleaning: The internals of your CPAP/ BiLevel unit do not need regular cleaning but you should be ensuring your CPAP / Bilevel unit is not becoming dusty. Wipe off any surface dust once per week along with ensuring you are changing your filters as recommended. A clean filter ensures the CPAP / Bilevel motor will function longer.
- o Replenishment: CPAP/ BiLevel machines have an anticipated life expectancy of 5 years, though can last longer with proper cleaning and care. Most extended health benefits plans will cover a new CPAP machine every 5 years. If it has been 5 years since you purchased your CPAP/ BiLevel machine, contact a MedPro representative and we can assist with a quote to your extended medical plan for a new CPAP/ BiLevel.
- Warranty: 3 years*

Thank you! If you are satisfied with the Medpro service provided to you, we would love for you to do a Google review

^{*} There is a small fee to ship your machine back to the manufacturer for warranty and out of warranty repairs

^{**} Device faults and failures due to improper maintenance and cleaning are not covered under warranty